

[] 2693-67
Copy 5 of 11

25X1A

19 October 1967

MEMORANDUM FOR THE RECORD

SUBJECT: Critique for OXCART Mission BX6727

1. Subject mission critique was conducted in the OSA Control Center at 1400, 13 October 1967.

2. Mission Data:

- a. Mission Number: BX6727
b. Date Flown: 6 October 1967
c. Area of Operation: North Vietnam
d. Mission Success: Successful
e. Pilot's Name: []
f. Aircraft Number: 131
g. Primary or Spare Flown: Primary
h. Takeoff Time - Planned: 06/0105Z
Actual: 06/0105Z
i. Landing Time - Planned: 06/0442Z (Kadena)
Actual: []
j. Time Enroute - Planned: 3+42
Actual: 2+20
k. Departure Base: Kadena AB
l. Landing Base: []
m. Equipment:

- (1) Primary: Type I, [] Sys VI
(2) Spare: Same as primary

3. Operations:

- a. Route (INS Plot vs. Planned): Satisfactory.

25X6

25X1A

2693-67
Page 2

25X1A

- (1) Comments: Excellent track.
- (2) INS Terminal Error: 2.8 NM for 2+50 nav time.
- (3) INS Spec Error: 4.8 NM

b. Mission Generation & Operational Support: Satisfactory.

(1) Comments: Pilot aborted after one pass over denied due to low oil pressure indication on right engine.

c. Other Comments: Mission recovered to Kadena 9 Oct 67 in-cell with KC-135.

4. Weather:

a. Forecast vs. Actual:

(1) As briefed.

(2) Comments: [] reported the target area Cat I and 40 percent cloud cover from the camera on point to off point for pass one. The forecast for [] was accurate and no recovery weather problems were experienced.

b. Weather Scout Reporting: Satisfactory.

5. Intelligence:

a. Target Coverage:

- (1) 10 of 24 programmed targets covered.
- (2) 1 first priority SSM target of 9 covered.
- (3) 6 of 27 first priority NVN COMOR targets covered
- (4) 10 SAM sites, 0 sites occupied, 0 new sites
- (5) 6 other priority NVN COMOR targets covered.
- (6) Comments: Obtained extensive observations of rolling stock.

b. Quality of Take: Satisfactory.

(1) Resolution: Good.

25X1

25X1A

[] 2693-67
Page 3

25X1A

(2) Camera Operation: 19 minutes of take. Light haze, no cages and 1711' film transported. Four 1/2 inch tears in post-flight position of mission. This occurred during down loading at []

25X1A

25X1

25X1D



25X1D

e. []

f. Take Movement:

(1) Photography: Satisfactory.

25X1



6. Materiel:

a. Aircraft General: Unsatisfactory.

(1) Comments: Air aborted []; right engine oil pressure slowly dropped to zero. Engine not shut-down. Discrepancy localized to indicator circuit from transmitter. Now localized to Bendix terminal box. No previous failures.

25X6

b. Aircraft Systems: Satisfactory.

7. Communications: Satisfactory.

a. Message Traffic: Satisfactory.

25X1

25X1A

OXCART/ []

HANDLE VIA []
COMINT CONTROL
CHANNELS JOINTLY

2693-67

Page 4

25X1A

(1) Comments: All traffic moved without difficulty.

25X1A

b. [] Satisfactory.

(1) Comments: System functioned as programmed.

c. UHF/HF Commo: Satisfactory.

d. Other Comments: Possible compromise of call signs investigated and cleared as no compromise.

8. Significant Actions Taken:

a. Aircraft recovery procedures are being reviewed by operations staff and will be the subject of separate actions (OXCART Division, OSA).

b. Weather scout identifiers/Area suffix are being changed each mission due to suspected pre-mission indicators to ChiCom Air Defense (OXCART Division, OSA).

9. Outstanding Actions Required:

25X1D

[]

25X1A

[]
WILLIAM E. SHELTON
Colonel, USAF
Deputy for Operations, OSA

25X1A

HANDLE VIA []

TOP SECRET

Approved For Release 2002/06/10 : CIA-RDP69B00404R000100190001-4

25

2693-67
Page 5

25X1A

25X1A OXC/O/OSA/:pm

Distribution:

- #1 - D/SA
- #2 - D/O/OSA
- #3 - D/M/OSA
- #4 - D/R&D/OSA
- #5 - OXC/O/OSA
- #6 - Intel/O/OSA
- #7 - Wea/O/OSA
- #8 - Commo/O/OSA
- #9 - ADP/O/OSA
- #10 - RB/OSA
- #11 - CHRONO

25X1A

OXCAR/

TOP SECRET

HANDLE VIA
CONTROL CHANNELS
JOINTLY

Approved For Release 2002/06/10 : CIA-RDP69B00404R000100190001-4